



ALTAIR ENGINEERING INSPECTIONS PTE LTD

7. Project Name: Casing Hanger Neoprene Coating

Client: Trelleborg/McDermott/Exxon-Qatar Gas-Singapore

Project Year: 2020-2021

Description

- The Project involved requires implementing **UT** in detecting Disbond between Neoprene Coating on casing hangers.
- Inspection scope-Neoprene coated Casing Hanger; Thickness-15-40mm
- Procedure & Technique developed with standard calibration & validation blocks fabrication.
- Validation of procedure, technique & operator qualification was done successfully with demonstration to McDermott, Exxon, Qatar Gas & Trelleborg representatives.
- Onsite Inspection activities were witnessed by Qatar Gas & Trelleborg representatives.
- Job Ref-D2014



Person Involved:

Procedure/Technique Sheet: Shaik Khaja Mohiuddin/Siraj Hameed Masroor/Mohsin

Technique Qualification: Ganesh/Martin/Meera/Aziz

Field Inspection: Ganesh/Martin/Meera/Aziz